June 11, 1981

Open Burning Observed at Acme Salvage in Ashtabula, Ohio (no request number)

Daniel C. Watson
THRU: A. R. Winklhofer, Director, EDO

Stephanie Valentine
Engineering Section, 5EAE

While or a June 2, 1981 water survey in Ashtabula, Charles Beier and Joseph Good of EDO noticed open burning at Acme Salvage and Scrap at State and Middle Roads. They noticed the burning from 1405 through 1420 EDST. The smoke was a very dense black and had a strong odor of burning rubber or insulation. Photographs were taken from Middle Road at a railroad crossing and will be sent at a later date.

The writer visited the site on May 21, 1981 on a complaint that the company was burning power transformers possibly containing PCB. During this visit a sight was found where transformers had been burned and PCB samples were collected. There were three unburned transformers at the facility during this visit.

Attachment

Chris Frazier, OEPA - NEDO

RECEIVED

JUN 15 1931

OHIO ENVIRONMENTAL PROTECTION AGENCY N. E. D. O.

JS EPA RECORDS CENTER REGION 5



OH ENVIRONMENTAL PROTECTION AGENCE COMPLAINT INVESTIGATION REPORT

<u>NEDO</u> District	Ashtabla County	6-10-8/ Date Received	Date(s) Investigated
TYPE cal itten tarized oudsman gislative her Official #	Air Ground Water Industrial Water Sewage Water Other	Craig X ALLEGED PO	Scrap
FICIALS CONTACTED:	(name, position, phon	e number, date and	time of contact)
nck-up truck was plo Fields Brook ad 55 gal drun orang From Hiem	ANT: A tan or brown cbscrued around 12:3 of State Pd. The is in the back will . The truck pulled . The truck	so bake truck h hoses from	OF ALLEGED POLLUTER:
DINGS: Justified	Not Justifie		
	•		
OPMENDATIONS:			

					IT INVESTIGATION REPORT	
DISTRICT	COUNTY	DATE RECE	LVED	DATE (S) IN	IVEST IGATED	
NEDO	Ashtabula	May 8,	1981	May 8,	1981	
TYPE Telephone Visit Letter Verified DCN Other	AIR Industrial Particulate Odor Fugitive Dust Open Burning X X Other	WATER Industrial Ground Sewage Other	Chris Ohio SUSPECTE Acme P.O.	Frazier EPA	Address, Phone) [ame, Address, Phone) 44004 998-2820	
	OF COMPLAINANT: dense, black smok	e pouring ou	it of s	crap yard.		
from a said th viously truck. 11:15 a INDINGS:	CEI transformer me employes must drained. He sa	had been acc have forgott id they were rry Tackett, approximate ustified Que	cidenta cen to e fight emplo ely 15 estionabl	lly ignited check if the ing the fir yee, the fing land in the fing land in the firm of the content of the content in the cont		
in the time of	yard behind a la	rge, gray bu on but the e	uilding	. The fire	was being watered at the not doing an adequate job	
					\	
ECOMMENDA					F WRITTEN FOLLOW UP May 19, 1981	_
quiring		ction of eve	ry tra	nsformer fo)" contain provision re- or left-over oil. Also	
ORRECTIVE	ACTION AGREED TO BY	SOURCE:		· · · · · · · · · · · · · · · · · · ·		
Inspect	all transformer	s for left-c	over oi	1.		
filled		ose." This	filling	g procedure	500 gal. water truck is severely hinders Acme	
NVESTIGAT	OR: Chris Frazie	r		DATE CO	OMPLETED: May 28, 1981	

cc: Dennis Lee, Ind. WW Melinda Becker, OLPC